



(short wire on pcb)

- Remarks
- If PFRA fuse has bad HF behaviour it can be removed
 - THS4509 has multiple Power pins, use 2 100n for each rail
 - Input diodes protect against HF overload
 - We may replace OPA656 with OPA659, ADA4817 or a JFET pair (AoE, p. 135, fig. 3.29)
 - 10n R2R for LMH6574 and LMH6703

DAD/DSO, Amplifier (Ch. 1)	
File: AmplifierCh1.sch	Sheet: 3 of 19
Author: S. Salewski	Rev: A 0.43
Copyright: All Rights Reserved	Date: 25-JUL-2010