



Remarks

- Flyback diodes are redundant
- 10n capacitors may be obsolete
- 47n/250V C0G should be fine -- no foil cap. necessary
- A 1.65V square signal is available for calibration
- Reed-Relays: Meder_SILxx-1A72-71D&Meder_DIPxx-1C90-51D
- Estimated Inductance of Reed Relays: 25nH -- series resistors are optimized for this value, fine tuning is necessary.

DAD/DSO, Input Divider (Ch. 1)	
File: InputDividerCh1.sch	Sheet: 1 of 19
Author: S. Salewski	Rev: A 0.43
Copyright: All Rights Reserved	Date: 21-SEP-2009